Check voltage display on 26 Pitmax and Midimax

- Push the + button & - button on the display together until it is flashing
- Press M until you get to PO3
- Push the + button until you get the voltage for your bike
- 72v for Pitmax
- 60v for MidiMax
- Push the + button & - button on the display together until it has stopped flashing
- You're all done!

